

●銅丸棒定尺

単位: mm

径	C1100B			
	タフピッチ銅棒			
	製造方法	調質	2000L	4000L
3	引抜	H	○	-
4	引抜	H	○	○
5	引抜	H	○	○
6	引抜	H	○	○
7	引抜	H	○	○
8	引抜	H	○	○
9	引抜	H	○	○
10	引抜	H	○	○
11	引抜	H	-	○
12	引抜	H	-	○
13	引抜	H	-	○
14	引抜	H	-	○
15	引抜	H	-	○
16	引抜	H	-	○
17	引抜	H	-	○
18	引抜	H	-	○
19	引抜	H	-	○
20	引抜	H	-	○
21	引抜	H	-	○
22	引抜	H	-	○
23	引抜	H	-	○
24	引抜	H	-	○
25	引抜	H	-	○
26	引抜	H	-	○
28	引抜	H	-	○
30	引抜	H	-	○
32	引抜	H	-	○
35	引抜	H	-	○
36	引抜	H	-	○
38	引抜	H	-	○
40	引抜	H	-	○
41	引抜	H	-	○
42	引抜	H	-	○
45	引抜	H	-	○
48	引抜	H	-	○
50	引抜	H	-	○
55	引抜	H	-	○
60	引抜	H	-	○
65	引抜	H	-	○
70	引抜	H	-	○
75	引抜	H	-	○
80	引抜	H	-	○
85	引抜	H	-	○
90	引抜	H	-	○
95	引抜	H	-	○
100	引抜	H	-	○
105	押出	F	2000L～乱尺	
110	押出	F	2000L～乱尺	
120	押出	F	2000L～乱尺	
130	押出	F	2000L～乱尺	
140	押出	F	2000L～乱尺	
150	押出	F	2000L～乱尺	
170	押出	F	2000L～乱尺	
180	押出	F	2000L～乱尺	

●黄銅丸棒定尺

単位: mm

径	C3604B		
	快削黄銅2種		
	製造方法	2000L	3000L
3	引抜	○	
4	引抜	○	
5	引抜		○
6	引抜		○
7	引抜		○
8	引抜		○
9	引抜		○
10	引抜		○
11	引抜		○
12	引抜		○
13	引抜		○
14	引抜		○
15	引抜		○
16	引抜		○
17	引抜		○
18	引抜		○
19	引抜		○
20	引抜		○
21	引抜		○
22	引抜		○
23	引抜		○
24	引抜		○
25	引抜		○
26	引抜		○
27	引抜		○
28	引抜		○
29	引抜		○
30	引抜		○
31	引抜		○
32	引抜		○
33	引抜		○
34	引抜		○
35	引抜		○
36	引抜		○
38	引抜		○
40	引抜		○
41	引抜		○
42	引抜		○
44	引抜		○
45	引抜		○
46	引抜		○
48	引抜		○
50	引抜		○
51	引抜		○
52	引抜		○
53	引抜		○
54	引抜		○
55	引抜		○
58	引抜		○
60	引抜		○

単位: mm

径	C3604B		
	快削黄銅2種		
	製造方法	2000L	3000L
62	押出		○
65	押出		○
70	押出		○
75	押出		○
80	押出	～ 3000Lまで	
85	押出	～ 3000Lまで	
90	押出	～ 3000Lまで	
95	押出	～ 3000Lまで	
100	押出	2500L～乱尺	
105	押出	2500L～乱尺	
110	押出	2500L～乱尺	
115	押出	2500L～乱尺	
120	押出	2500L～乱尺	
130	押出	2500L～乱尺	
140	押出	2500L～乱尺	
150	押出	2500L～乱尺	
160	押出	2500L～乱尺	
180	押出	2500L～乱尺	
200	押出	2500L～乱尺	

上記にないサイズもお問合せください